



Accessory Circular

Subject: Trailer Control Module for Touareg #7L0907383E

Number: 002-08-05 UC

Date: 9/12/2005

Attention: VW Service and Parts Managers:

Subject: Requirement to return trailer Control Module for Touareg Part number 7L0 907383 E

Effective immediately, when you are installing trailer hitch kit #7L0092101U, please inspect the control module that is included in the kit. If the part number 7L0907383E appears on the control module, you need to order in a new replacement control unit 7L0907383G with hardware code (HW54) and Software (SW088). The newer index "G" part number does not require flashing.

Please claim the part number 7L0907383E under warranty, and as it is under submission, return it to the:

Volkswagen of America, Inc.

Warranty Test Center

3800 Hamlin rd

Auburn Hills, MI 48326

The reason for this requirement is that With the Base CD 7.01(or higher) level for the 5051 the flashing of the control module in accordance with TB Group:01 Number: 05 -12 Date July 27. 2005 is no longer possible.

Once the 5051 scan tool software has been properly updated, or the stock of 7L0092770UA is completely depleted (whichever comes first), a change in process will be published.

It is also important to note that the new version of the Dealer Installed Trailer Hitch p/n# 7L0092 105UA has the newer 7L0907383G in it.

Thank you for your collaboration with this matter.

Your Volkswagen Accessories Development Team.