

DX-70TH External Amplifier Relay Modification

Locate and Cut R505 to Enable External
Relay Triggering.

